

# Troubleshooting

## Wall Sawing and Floor Sawing

Good product selection, regular observation and maintenance are the keys to obtaining maximum life from wall and floor saw blades. The following notes should assist you to obtain the maximum life expectancy from blades and help keep within Health and Safety guidelines at all times.


Blades should be checked regularly for cracks, discolouration and signs of overheating or undercutting. All these faults could lead to segment loss, after which it is unsafe to use the blade further.

As most problems occur as a result of incorrect blade choice, inappropriate usage and faults with the equipment (e.g. motor, machine stability and water/coolant supply), particular attention should be paid to these aspects and to the manufacturer's instructions before sawing commences. When problems occur during usage, the following aspects should be checked as the most obvious causes and solutions, and the machine stopped to avoid further damage. If these immediate 'first aid' measures do not solve the problem, please call the Diaquip Technical Services Dept. for further advice. Do not use the machine again until this is obtained.

## Whole blade performance

### PROBLEMS ENCOUNTERED

#### A. LOSS OF TENSION / BLADE DISTORTION



### POSSIBLE CAUSES

1. Saw is not properly aligned.
2. Blade/bond is too hard for the material being cut leading to excessive stress.
3. Attempt is being made not to cut in a straight line.
4. Material has slipped and caused blade to buckle.
5. Fixing flanges are not of correct size, balanced or aligned.
6. Blade not properly fitted to spindle.
7. Excessive or uneven wear at blade circumference puts pressure on the core.
8. Steel core overheating or not sufficiently water-cooled.
9. Excessive speed/rpm being attempted.
10. Pre-cut blade has not been used to prepare for deeper cuts.
11. Blade damaged or dropped during transport or handling.


### CORRECTIVE MEASURES

1. Realign.
2. Select correct blade.
3. Ensure cutting is straight and blade at 180° to material being cut.
4. Ensure that material to be cut is firm and stable.
5. Ensure that flanges are of correct size, uniformly fitted and adequately (but not excessively) tightened.
6. Ensure blade is fitted to spindle without excessive play or tightness.
7. Check wear patterns regularly and replace/repair as necessary.
8. Check cooling system and water distribution.
9. Reduce speed.
10. Use pre-cut blade whenever possible or appropriate.
11. Check blades carefully before use. Replace/repair as necessary.

**PROBLEMS ENCOUNTERED**

**B. UNDERCUTTING**

*This describes the situation when the steel cores/centres wear more rapidly than the segments on the circumference. It can lead very rapidly to segment loss.*



**POSSIBLE CAUSES**

1. Incorrect choice of blade material – bond too soft.
2. Cutting into substrate (may lead to loss of coolant).
3. Rotation direction incorrect.
4. Incorrect water pressure or supply.
5. Very abrasive materials being cut.

**CORRECTIVE MEASURES**

1. Select correct blade.
2. Reduce depth of cut to minimum necessary to prevent cutting through abrasive debris (protective segments may be used to protect the blade in extreme cases).
3. Correct direction of rotation.
4. Check cooling system and water distribution.
5. See 2 above.

**C. OVERHEATING**


*This can easily be detected by noting a black or blueish discoloration of the steel core.*



1. Attempting to cut too fast or too deeply in one pass.
2. Bond too hard – can lead to 'pounding'.
3. Excessive feed pressure.
4. Blade spinning freely on spindle.
5. Shaft worn, grooved or damaged.
6. Water pressure too low, flow insufficient or unevenly distributed.
7. Blade cut too deep – no coolant reaching cutting edge.

1. Do not be too ambitious in depth of cut which is possible at one pass. Multiple shallow cuts may take longer, but will protect the equipment and are quicker in the long run.
2. Select correct blade for material to be cut.
3. Reduce feed pressure.
4. Correct fit of blade to spindle.
5. Replace or repair.
6. Check cooling system and water distribution.
7. Reduce depth of cut. See 1 above

**D. BLADE WILL NOT CUT**




1. Bond too hard / blade being used on wrong material, leading to bluntness – blade becomes 'glazed'.
2. Machine power inadequate for task (wrong motor, voltage or belt tightness).
3. Incorrect or altered direction of cut, leading to jamming.
4. Segments missing or badly worn.
5. Segments have become smooth and are not cutting, even though not fully worn.
6. Excessive coolant causing blade to float or aquaplane.
7. Excessive motion or play between the carriage guides.
8. Insufficient feed pressure / rate.
9. Freeback has been reached.
10. Incorrect direction of rotation.
11. Water pressure too low, flow insufficient or unevenly distributed.

1. Select correct blade to achieve the correct bond. Open-up glazed segments by working briefly on very abrasive material.
2. Select correct motor capacity and voltage: check belt tightness.
3. Realign direction / angle of cut.
4. Repair blade and replace segments if possible. Otherwise, replace blade.
5. Open up glazed segments by working briefly on very abrasive material.
6. Reduce flow of coolant.
7. Realign and tighten carriage guides.
8. Increase feed pressure / rate.
9. Blade is worn out, replace blade.
10. Correct direction of rotation.
11. Check cooling system and water distribution.

**PROBLEMS ENCOUNTERED**

**E. WOBBLE / FLUTTER**



**POSSIBLE CAUSES**

1. Flexing due to excessive feed or rotational speed.
2. Flanges incorrectly fitted/tightened/balanced (could also be due to debris being trapped between flange and blade – check for this).
3. Incorrect mounting of blade on shaft – problem compounded when flanges are tightened.
4. Shaft bearing worn or damaged.
5. Blade tension does not match cutting speed.
6. Blade tension lost, leading to flutter and further distortion when speed increased.

**CORRECTIVE MEASURES**

1. Reduce speed and monitor performance.
2. Correct flange fittings and remove any debris trapped between flange and blade.
3. Mount blade correctly. Do not tighten flanges excessively.
4. Replace or repair.
5. Re-tension blade in balance with cutting speed.
6. Recalibrate blade tension.

**F. BLADE DISTORTION / RUNNING OUT-OF-ROUND / DAMAGE TO THE ARBOR OR BORE**


*(Check against the causes listed under e) above, and also consider the following additional possibilities).*



1. Bond too hard, causing diamonds to become prematurely worn and smooth. This leads to 'pounding' and loss of blade shape.
2. Arbor hole does not match shaft diameter or has become worn.
3. Drive pin not fitted to rear flange or properly located in its retaining hole.
4. Motor not correctly tuned.
5. Blade spinning on spindle shaft or running loose.
6. Blade spindle grooved or damaged, leading to eccentric running.
7. Inadequate lubrication to spindle bearings (especially when sawing concrete).

1. Select correct blade for the material being cut.
2. Rematch arbor and shaft. Repair or replace arbor if worn.
3. Ensure that all drive pins are correctly located in their mounting holes.
4. Retune machine motor.
5. Check that blade core fits snugly onto its drive shaft.
6. Replace or repair damaged blade spindle
7. Improve lubrication to bearings.

**G. CRACKING TO THE CORE**



1. Bond too hard.
2. Excessive feed pressure or rotational speed.
3. Core loses tension because of excessive heat load (see C on previous page).
4. Core distorted through incorrect line of cut.
5. Damaged bearing or faulty mounting.
6. Blade twists or jams in cut

1. Select correct blade for material to be cut.
2. Reduce feed pressure and/or speed.
3. Reduce speed and check coolant supply.
4. Correct line of cut.
5. Replace or repair bearing / mounting.
6. Remove blade, allow to cool and check coolant/lubrication.

## Segment Faults

### PROBLEMS ENCOUNTERED

#### A. SEGMENTS 'GLAZED' – WON'T CUT




### POSSIBLE CAUSES

1. Bond too hard – can lead to pounding and fracture of segments.
2. Blade has 'dulled' and diamonds need to be 'opened up'.
3. Insufficient feed pressure.
4. Freeback has been reached.
5. Insufficient power to blade.
6. Incorrect direction of rotation.
7. Speed of rotation too high.
8. Water pressure insufficient.

### CORRECTIVE MEASURES

1. Select correct blade for material bond.
2. Open up glazed segments by working briefly on very abrasive material.
3. Increase feed pressure.
4. Freeback is not a fault. Select new blade.
5. Increase power to blade.
6. Correct direction of rotation.
7. Reduce speed of rotation.
8. Increase water pressure.


#### B. SEGMENT LOSS



1. Line of cut is not straight.
2. Bond too hard – can lead to pounding and fracture of segments.
3. Failure to notice segment cracks.
4. Excessive feed pressure.
5. Flanges worn / insufficiently or unevenly tightened.
6. Out-of-round wear pattern.
7. Material slips during cutting.
8. Eccentric wear pattern on blade core.
9. Segment damaged or loosened during transit.
10. 'Undercutting'.

1. Improve straightness of cut.
2. Select blade and bond suitable for the material to be cut.
3. Check appearance of segments regularly and replace/repair when necessary.
4. Reduce feed pressure.
5. Ensure flanges of the correct size, balance and tightness during operation.
6. Check spindle and core correctly centred.
7. Ensure material is held rigid during cutting.
8. Check spindle and core correctly centred. Replace spindle if necessary and/or fit new bearings.
9. Always check blades and segments before usage.
10. Reduce depth of cut to minimum necessary to prevent contact with abrasive sub-base (protective segments may be used to protect the blade in extreme cases).

#### C. SEGMENT CRACKS



1. Arbor hole does not match shaft diameter.
2. Excessive feed pressure.
3. Rotation speed too high.
4. Worn, grooved or damaged shaft.
5. Excessive machine vibration or instability.
6. Problems with coolant supply.

1. Ensure snug fit between arbor and shaft. Replace if necessary to ensure this.
2. Reduce feed pressure.
3. Reduce rotation speed.
4. Replace or repair shaft.
5. Ensure stability of machine. Operate at low speed initially and monitor performance.
6. Check cooling system and water distribution.

## PROBLEMS ENCOUNTERED

### D. EXCESSIVE WEAR



## POSSIBLE CAUSES

1. Incorrect match of material and blade – bond too soft.
2. Excessive feed pressure causing blade to flex.
3. Misalignment of blade and machine.
4. Out-of-round wear pattern.
5. Rotation speed too low or loose/slipping drive belts.
6. Worn, grooved or damaged shaft.
7. Excessive machine vibration or instability.
8. Blade not at 180° to material being cut.

## CORRECTIVE MEASURES

1. Select correct blade with harder bond.
2. Reduce feed pressure.
3. Realign blade and machine.
4. Check spindle and core correctly centred. Replace spindle if necessary and/or fit new bearings.
5. Increase rotation speed. Check and tighten drive belts.
6. Repair or replace shaft.
7. Ensure stability of machine. Operate at low speed initially and monitor performance.
8. Ensure blade cuts directly onto material.

### E. UNEVEN SEGMENT WEAR



1. Excessive feed pressure.
2. Flanges not holding blade properly.
3. Misalignment of blade and shaft.
4. Worn, grooved or damaged shaft.
5. Blade spinning on spindle – drive pin not engaged.
6. Water pressure too low, flow insufficient or unevenly distributed.

1. Adjust feed pressure.
2. Ensure flanges of the correct size, balance and tightness during operation.
3. Realign blade and shaft.
4. Repair or replace shaft.
5. Ensure that all drive pins are correctly located in their mounting holes.
6. Check cooling system and water distribution.